


ASSEMBLY AUTOMATION®



Linear Bearings
Through out

Air or Electric
Torque Motors

Quick Change
Screwdriver Mounts

Compression Spindles

Quick Release Bit Holders

Depth Check On Each Spindle

Compact Head Tooling

Ground Steel Base

Junction Box

TS 9000
Multi Head Screwdriver

